

## S-99 Reports for 2011

In accordance with regulatory document entitled S-99 Reporting Requirements for Operating Nuclear Power Plants, power reactors operating in Canada must issue formal reports to the Canadian Nuclear Safety Commission (CNSC) on events defined in the S-99 regulatory guideline document.

The following is a list of S-99 – Event Reports – that were generated for NB Power Nuclear -- Point Lepreau Generating Station operations in 2011.

NB Power Nuclear provides an update to this list on a quarterly basis.

### Significant Development Reports

In some instances S-99 events are the subject of Significant Development Reports and are presented by CNSC staff to the CNSC Commission at a public meeting. These events are typically ones which have higher potential. Significance or that may raise public interest. Those S-99 events which were Significant Development Reports will be highlighted in blue in the S-99 event listing.

### Questions?

For more information on the Event Reports listed, Event Reports from prior years or other reports on NB Power Nuclear's operations, contact **Kathleen Duguay, Manager of Public Affairs** at 506-659-6433.

## Point Lepreau Generating Station 2011 S-99 Reporting

Event Number	Description
ERD-67140-1011-024-A-00	Fire Alarm Logic Discrepancies Identified
ERD-00583-1012-009-A-00	Change to a Station Instruction without Regulatory Approval
ERD-73140-1101-012-A-00	Maintenance Non-compliance with Code Requirements of Pressure Boundary Program
ERD-03400-1101-014-A-00	Leak Tests not Performed on Stored Shielding Containing Nuclear Substances
ERD-71500-1101-24A-A-00	Administration Building Domestic Hot Water
ERD-01347-1102-003-A-00	Equipment Program Plan for Safety Relief Valves does not meet CSA N285.0-2006 Requirements
ERD-03400-1102-009-A-00 (HP)	Radiation Area Not Signposted
ERD-71310-1102-021-A-00	Pressure Safety Valve (PSV) Failed to Operate on its "As Found" First Set Pressure Test
ERD-03400-1102-025-A-00	Radiation Area Not Signposted
ERD-03641-1103-010-A-00	Transition to CSA N295.4-09 Periodic Inspection of CANDU Nuclear Power Plant Components
ERD-34810-1103-018-A-00	Liquid Zone Control (LZC) System Overpressure Protection

ERD-00583-1103-031-A-00	Emergency Response Team Minimum Complement
ERD-00105-1104-012-A-00	Emergency Response Team Minimum Shift Complement
ERD-00105-1104-020-A-00	Non-Certified Operators Qualification Tracking
ERD-00105-1104-021-A-00	Senior Power Plant Operator Qualification
ERD-71400-1105-017-A-00	1 Fire Protection Zone Unnecessarily Selected To "Local" Control
ERD-67141-1010-08A-A-00	Secondary Control Area Fire Panel Deficiencies
ERD-00583-1106-010-A-00	Emergency Response Team Minimum Shift Complement
ERD-71400-1106-013-A-00	Fire Protection Zone 51 Found Isolated
ERD-00105-1106-023-A-00	Emergency Response Team Leader Requalification
ERD-00105-1107-025-A-00	Emergency Response Team Minimum Shift Complement
ERD-60210-1108-008-A-00	Unapproved Modifications to a Public Address Speaker
ERD-00105-1108-025-A-00	Emergency Response Team Minimum Shift Complement
ERD-41130-1112-001-A-00	<i>Preliminary Information</i> - Release of Light Water Containing Hydrazine of the Environment

### Preliminary Information

ERD-41130-1112-001-A-00	Release of Light Water Containing Hydrazine of the Environment <a href="#">(click here for more details)</a>
-------------------------	---